

FY23 USAF & USSF CONSTRUCTION TASKING ORDER							
MAJCOM	Installation	Project Number	Project Title	Execution Agent	Execution Method	Remarks	CTO/UPL
Estimated Project Value < \$100K							
ACC	SI EUSTIS	HERT212522	Demo 2.056 SF B821	Base	DB	Demolition	CTO
AETC	COLUMBUS AFB	EEP2132020I	DSN-ADD/ALTER PAINT BARN DECONTAMINATION AREA, B406	USACE	DBB	Design	CTO
AETC	JB SAN ANTONIO	TYMX190063	DSN-Construct T7A Munitions Storage Facility	Base	DB	Design	CTO
AFGSC	DYESS AFB	FNWZ210074	Demolish FORMER C-130 GP SHOP 4308	Base	DB	Demolition	CTO
AFGSC	DYESS AFB	FNWZ210080	Demolish GENERATOR BUILDING 9114	Base	DB	Demolition	CTO
AFMC	ARNOLD AFB	ANZY170019	DSN-REPAIR NON CODE COMPLIANT FIXED LADDERS 3400 AREA, MUL	Base	DBB	Design	CTO
AFMC	EDWARDS AFB	FSPM19PS067	DEMOLISH INERT MUNITIONS STORAGE B639	Base	DB	Demolition	CTO
AFMC	EGLIN AFB	FTFA22TM05	Gate 1D DEMOLISH WAREHOUSE BLDG 6020	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM214488	Demo B1494	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM214495	Demo B2006	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM217071	Demo B2107	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM217073	Demo B2108	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM217076	Demo B2131	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM217077	Demo B2132	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM217078	Demo B2138	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM217079	Demo B2204	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM217080	Demo B2206	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM217082	Demo B2207, B2227	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM214493	Demo B936	Base	DB	Demolition	CTO
USAFE	AVIANO AB	ASHE211043	DSN-EXPAND SIERRA ARM/DEARM	Base		Design	CTO
USAFE	AVIANO AB	ASHE173001	DSN-INSTALL PHOTOVOLTAIC SYSTEMS ON HANGARS 5, 6 ROOFS	Base		Design	CTO
USAFE	INCIRLIK AB ADANA	LYC211043	DEMO END OF RUNWAY BUILDING 2208	Base	DBB	Demolition	CTO
USAFE	RAMSTEIN AB	MTMC211572	DSN-ADD/ALTER BUILDING #698 (DEMO B#697)	LBB		Design	CTO
USAFE	RAMSTEIN AB	TYFR171043	REMOVE 2 EA UST'S	Base	DB	Construction	CTO
USSF	RAMSTEIN AB	TYFU210518	CONSTRUCT ANTENNA FOUNDATION, NEAR B# 2849	TBD		Construction	CTO
USSF	VANDENBERG SFB	XUMU091309	Demo Missile Storage Facility, B1181-B1183	Base		Demolition	CTO
AFMC	HILL AFB	KRSM193953	Repair Bollard Lights at Dorm Campus	TBD		Construction	UPL
AFMC	HILL AFB	KRSM182645	REPAIR CEMENT WALKWAYS NEAR BUILDING 365	TBD		Construction	UPL
Estimated Project Value \$100K - \$250K							
ACC	CREECH AFB	LKTC191001	DEMOLISH HQ ADMIN BUILDING 12AF B55	Base	DB	Demolition	CTO
ACC	NELLIS AFB	RKMF220089	DSN - CONSTRUCT BEDDOWN SITE 800 RHG (RH)	Base		Design	CTO
ACC	NELLIS AFB	RKMF240006	DSN-CONSTRUCT VEHICLE STORAGE & MAINTENANCE FACILITY PEB (R	Base		Design	CTO
ACC	SI EUSTIS	HERT202645	DSN-Repair Matthew Jones House, B1611	Base	DBB	Design	CTO
AFGSC	DYESS AFB	FNWZ210072	Demolish Communications Facility 9030	Base	DB	Demolition	CTO
AFGSC	MALMSTROM AFB	NZAS101040	DEMO Demolish Bldg 1192, Family Support Center	TBD		Demolition	CTO
AFMC	EGLIN AFB	FTFA171070	DSN-REPAIR UPDATE FOAM FIRE SUPPRESSION & HVAC SYSTEMS B985	Base	DBB	Design	CTO
AFMC	HILL AFB	KRSM217055	Demo B1471	Base		Demolition	CTO
AFMC	HILL AFB	KRSM180010	DSN-Renovate Youth Center B883 (NAF Companion)	Base	DBB	Design	CTO
AFMC	ROBINS AFB	UHHZ200052	DSN-CNSLD/DEMO RENOV/PAIN BUILDING 8, MUN MAINT ADMIN, B	Base	DBB	Design	CTO
AFMC	TINKER AFB	WWWYK170125	DSN-REPAIR HVAC SYSTEM AT CDC EAST, B3904	TBD		Design	CTO
PACAF	KADENA AB	LXEZ121734	DSN-REPAIR AIR MAIL TERMINAL, B215	USACE		Design	CTO
PACAF	KUNSAN AB	MLWR251003	DSN-RENOVATE CORROSION CONTROL FACILITY, B2820	USACE		Design	CTO
USAFE	AVIANO AB	DRBY211001	DSN-REPLACE WOOD STORAGE BLDG 2021, CAMP DARBY	USACE		Design	CTO
USAFE	INCIRLIK AB ADANA	LYC131067	DSN-REPAIR DORM 962 - DESIGN ONLY	Base	DBB	Design	CTO
USAFE	INCIRLIK AB ADANA	LYC241070	DSN-RPR DORM 964 - DESIGN ONLY	Base	DBB	Design	CTO
USAFE	INCIRLIK AB ADANA	LYC091074	DSN-RPR DORMITORY 885 - DESIGN ONLY	Base	DBB	Design	CTO
USAFE	MORON AB	QUUG191003	DSN-CNS NON-POTABLE WATER TANK	Base	DBB	Design	CTO
USAFE	RAF CROUGHTON	EXSW201011	DSN-Renovate Dormitory, Building 141	Base	DB	Design	CTO
USAFE	RAF CROUGHTON	EXSW201010	DSN-Renovate Dormitory, Building 142	Base	DB	Design	CTO
USAFE	RAMSTEIN AB	TYFR201125	CONSTRUCT TRAFFIC CIRCLE ILLINOIS BLVD./NEW YORK AVE./RODRIG	CTS	DB	Construction	CTO
USAFE	RAMSTEIN AB	MTMC171519	REPAIR EXTERIOR WALLS, B#687	CTS	DB	Construction	CTO
USSF	VANDENBERG SFB	XUMU111295	DEMO MSL/SPACE RSCH ENG. Fac 1785	Base		Demolition	CTO
USSF	VANDENBERG SFB	XUMU11108203	Demolish Dorm Postal Office, Bldg 13222	Base		Demolition	CTO
USSF	VANDENBERG SFB	XUMU051321	HLDT-Demolish Ground Guidance Facility	Base		Demolition	CTO
ACC	SI EUSTIS	HERT212535	Demolish B516	TBD		Demolition	UPL
AETC	GOODFELLOW AFB	JCGU204011	REPAIR DORM INTERIOR FINISHES, B238	Base		Construction	UPL
AFMC	HILL AFB	KRSM193043	REPAIR DORM ROOF, bldg 348	TBD		Construction	UPL
AFMC	HILL AFB	KRSM193044	REPAIR DORM ROOF, Bldg 364	TBD		Construction	UPL
Estimated Project Value \$250K - \$500K							
ACC	SI EUSTIS	HERT199001	Demo 10,387 SF B2732	Base	DB	Demolition	CTO
AETC	KEESLER AFB	MAHG211009	DSN-Replace AHU's and VAV's in NPS Dorms Ph I	Base		Design	CTO
AETC	LUKE AFB	HXCZ192200	DSN-REPAIR AIRFIELD LIGHTING SYSTEM, GILA BEND AFAP	Base	DB	Design	CTO
AETC	VANCE AFB	XTLF231017	Gate 2B - Demolish B300, B301, B303, B307, B309	Base	DBB	Demolition	CTO
AFDW	JB ANDREWS	AJXF211503	DSN-REPAIR DORMITORY 1692	TBD	DBB	Design	CTO
AFGSC	MALMSTROM AFB	NZAS111004	Demolish Bldg 1705, Maintenance Contractor Facility	TBD		Demolition	CTO
AFMC	EDWARDS AFB	FSPM181434	DSN-MC ADD/ALTER MWD KENNEL COMPLEX B3522	Base		Design	CTO
AFMC	EDWARDS AFB	FSPM19PS047	MC INSTALL EMERGENCY GENERATOR AFRL DATA CENTER B8352	Base		Construction	CTO
AFMC	EDWARDS AFB	FSPM22PS005	RPR DORM 2515	TBD		Construction	CTO
AFMC	EDWARDS AFB	FSPM22PS006	RPR DORM 2516	TBD		Construction	CTO
AFMC	EGLIN AFB	FTFA21CB67	DSN-REPAIR EXTERIOR ENCLOSURE, ROOFING, HVAC, FIRE PROTECTIO	Base	DBB	Design	CTO
AFMC	EGLIN AFB	FTFA20CB86	DSN-REPAIR EXTERIOR WALLS, ROOF, AND ELEVATORS B380	Base	DBB	Design	CTO
AFMC	EGLIN AFB	FTFA171080	DSN-REPAIR UPDATE FIRE FOAM SUPPRESSION SYSTEM HANGAR B315	Base	DBB	Design	CTO
AFMC	EGLIN AFB	FTFA22TM01	Gate 1D DEMOLISH VISITING OFFICER'S QUARTERS BLDG 10875	Base	DB	Demolition	CTO
AFMC	EGLIN AFB	FTFA22TM02	Gate 1D DEMOLISH VISITING OFFICER'S QUARTERS BLDG 10876	Base	DB	Demolition	CTO
AFMC	HILL AFB	KRSM100027PE	DSN-Repair Incoming Defueling Apron B10287 PHASE E	Base		Design	CTO
AFMC	ROBINS AFB	UHHZ160096	DSN-DEMOLISH SEWAGE SYS, WST TRMT BLDG, 8320	Base	DBB	Design	CTO
AFMC	ROBINS AFB	UHHZ160138	DSN-RPR/CORRECT DRAINAGE, STRM DRN DSPL, FCLTY8700	Base	DBB	Design	CTO
AFMC	WRIGHT PATTERSON AFB	ZHTV160004	DSN-REPAIR/REPLACE HVAC NASIC F/34023	Base	DBB	Design	CTO

FY23 USAF & USSF CONSTRUCTION TASKING ORDER							
MAJCOM	Installation	Project Number	Project Title	Execution Agent	Execution Method	Remarks	CTO/UPL
AMC	JB MCGUIRE DIX LAKEHURST	PTFL111017	DSN-REPAIR DORMITORY B2424	Base		Design	CTO
PACAF	KADENA AB	LXEZ211040	DEMO FACILITIES BASEWIDE	TBD	DB	Demolition	CTO
PACAF	KADENA AB	LXEZ191033	DSN-REPAIR AWACS/RC-135 HANGAR, B3660	Base	DBB	Design	CTO
PACAF	KADENA AB	LXEZ211049	DSN-REPAIR MARSHALL DFAC, B178	Base	DBB	Design	CTO
PACAF	KUNSAN AB	MLWR151006	DSN-RENOVATE DORMITORY, BLDG 342	TBD		Design	CTO
PACAF	KUNSAN AB	MLWR241004	DSN-RENOVATE DORMITORY, BLDG 344	TBD		Design	CTO
PACAF	SI OSAN	SMYU211102	DEMO ABANDONED B708	Base		Demolition	CTO
PACAF	SI OSAN	SMYU211103	DEMO ABANDONED B712, 721	Base		Demolition	CTO
PACAF	SI OSAN	SMYU211119	DSN-EXTEND NATURAL GAS PIPELINES ON THE WEST SIDE OF BASE	USACE		Design	CTO
PACAF	SI OSAN	SMYU211116	DSN-REPAIR FUEL TANKS & CERTIFIED INSPECTION, BASE-WIDE	USACE		Design	CTO
PACAF	SI OSAN	SMYU211117	DSN-REPAIR SEWAGE LIFT STATIONS, B659, B823 & B1356	USACE		Design	CTO
PACAF	SI TAEGU	WNHQ211102	DSN-REPAIR REFUELING VEHICLE MAINTENANCE SHOP, B-2356	USACE		Design	CTO
USAFE	INCIRLIK AB ADANA	LYC231096	DSN-RPR/REPLACE MAIN SUBSTATION, BLDG 3610	Base	DBB	Design	CTO
USAFE	LAJES FIELD	MQNA201005	DSN-EFFICIENCY - Repair LRS Admin & Warehouse Facility, T-608	Base	DBB	Design	CTO
USAFE	LAJES FIELD	MQNA131000	EFFICIENCY - Convert T-827, HAZWASTE, to AGE Maintenance	Base	DB	Construction	CTO
USAFE	MORON AB	QUUG171023	RPR APRON MARKINGS, 1443	CTS	DB	Construction	CTO
USAFE	RAMSTEIN AB	TYFR091213	DSN-RENOVATE DORMITORY, B#2104	LBB	DBB	Design	CTO
USAFE	RAMSTEIN AB	TYFR211156	MODERNIZATION/REPAIR RESTROOMS, B#2231	CTS	DB	Construction	CTO
USSF	PETERSON SFB	TDKA191005	CONSTRUCT GENERATOR N/NC, B2	Base	DBB	Design	CTO
AFMC	HILL AFB	KRSM193051	REPAIR BRICK WALLS AND CONCRETE WALKWAY IN DORM, Bldg 361	TBD		Construction	UPL
AFMC	HILL AFB	KRSM193049	REPAIR BRICK WALLS AND CONCRETE WALKWAY IN DORM, Bldg 363	TBD		Construction	UPL
AFMC	HILL AFB	KRSM193052	REPAIR BRICK WALLS AND CONCRETE WALKWAY IN DORM, Bldg 365	TBD		Construction	UPL
AFMC	HILL AFB	KRSM193951	Repair Dorm Campus Parking Lot	TBD		Construction	UPL
Estimated Project Value \$500K - \$1M							
ACC	MOUNTAIN HOME AFB	QYZH090007A	Demolish, CAC, B2618	Base	DBB	Demolition	CTO
ACC	MOUNTAIN HOME AFB	QYZH220009	TTP- Add/Alt Beddown Training Site, F4995	RHS		Troop Training	CTO
ACC	SI MOODY	QSEU200101	DSN-Repair Dorm, B324	Base	DBB	Design	CTO
AETC	JB SAN ANTONIO	MPLS196791	DSN-Repair Permanent Party Dorm, B1212	Base	DBB	Design	CTO
AFMC	EDWARDS AFB	FSPM22P5004	RPR DORM 2514	TBD		Construction	CTO
AFMC	EGLIN AFB	FFA22TM03	Gate 1D Demo AIRCRAFT SUPPORT VEHICLE MAINTENANCE SHOP BLD	Base	DB	Demolition	CTO
AFMC	SI HANSCOM	UQHH180085	Construct Access Control, Sagamore Hill	Base	DBB	Construction	CTO
AFMC	WRIGHT PATTERSON AFB	ZHTV100013	DSN-REPAIR EXTERIOR & WINDOWS HQ AFLCMC F/20014	Base	DBB	Design	CTO
AFMC	WRIGHT PATTERSON AFB	ZHTV150051	DSN-REPAIR HVAC/RENOVATE PZ/PK, F/30001	Base	DBB	Design	CTO
AFMC	WRIGHT PATTERSON AFB	ZHTV212729	DSN-TTP - Convert Shoulder Pavement to Apron Pavement Adjacent to	Base	DBB	Troop Training	CTO
AFMC	WRIGHT PATTERSON AFB	ZHTV180034	DSN-TTP - Repair Airfield East Ramp Section T25A	Base	DBB	Troop Training	CTO
AFMC	WRIGHT PATTERSON AFB	ZHTV130029	GATE 1B, DEMO F/20030	USACE	DB	Demolition	CTO
AFSOC	HURLBURT FIELD	FTEV201005	DSN-Renovate Dormitory, B90369	USACE	DB	Design	CTO
AMC	MCCONNELL AFB	PRQE231001	DSN-REPAIR Dormitory B350	Base		Design	CTO
PACAF	EARECKSON AS	VNMH170001	DSN-Repair Airfield Drainage and Shoulders	AFCEC	DBB	Design	CTO
PACAF	EARECKSON AS	YGFZ180016FA	DSN-Repair Industrial Area Sewer System	AFCEC	DBB	Design	CTO
PACAF	KADENA AB	LXEZ193438	DSN-REPAIR AIRCRAFT FIRE FIGHTER TRAINING FACILITY	Base	DBB	Design	CTO
PACAF	SI OSAN	SMYU211081	DEMO ABANDONED B1351, 1352, & 1353	Base		Demolition	CTO
PACAF	SI OSAN	SMYU211079	DEMO ABANDONED B1365 & 1366	Base		Demolition	CTO
PACAF	SI OSAN	SMYU211111	DEMO ABANDONED B1436, 1437 & 1438	Base		Demolition	CTO
PACAF	SI OSAN	SMYU201032	DSN-REPAIR NCO DORMITORY, B383	TBD		Design	CTO
PACAF	SI TAEGU	MMFZ181306	DSN-REPAIR UNACCOMPANIED PERSONNEL QUARTERS, B-241	USACE		Design	CTO
USAFE	LAJES FIELD	MQNA211006	EFFICIENCY - Convert T-169 into Laundry & FMO	Base	DB	Construction	CTO
USAFE	MORON AB	QUUG211009	MEA: ADD DISTRO TRANSFORMERS, B212	Base	DB	Construction	CTO
USAFE	RAMSTEIN AB	MTMC211572	ADD/ALTER BUILDING #698 (DEMO B#697)	LBB	DB	Construction	CTO
USAFE	RAMSTEIN AB	TYFR181017	SUS REPAIR OLD TWY_03/SW AREA	CTS	DB	Construction	CTO
USSF	CLEAR AIR STATION	DXEB191004	CONSTRUCT AMBULANCE BAY	TBD		Construction	CTO
AFGSC	VANDENBERG AFB	XUMU141098C	Add Pre-engineered Metal Storage Facility, Bldg 2010	TBD		Construction	UPL
AFMC	HILL AFB	KRSM182385	REPAIR BRICK WALLS AND CONCRETE WALKWAY IN DORM, Bldg 345	TBD		Construction	UPL
AFMC	HILL AFB	KRSM090031	REPAIR DORM ROOF, Bldg 345	TBD		Construction	UPL
AFMC	HILL AFB	KRSM193046	REPAIR DORM ROOF, Bldg 361	TBD		Construction	UPL
AFMC	HILL AFB	KRSM193045	REPAIR DORM ROOF, Bldg 365	TBD		Construction	UPL
AFMC	HILL AFB	KRSM193047	REPAIR DORM ROOFS, Bldg 363	TBD		Construction	UPL
USSF	VANDENBERG SFB	XUMU181030C	Install Counter Mobility Barriers B8510	TBD		Construction	UPL
Estimated Project Value \$1M - \$5M							
ACC	HILL AFB	KRSM178024	REPAIR F-35 HANGAR FLOOR B45	Base	DBB	Construction	CTO
ACC	MOUNTAIN HOME AFB	QYZH220011	TTP-Repair N-S Sterile Runway 31024	RHS		Troop Training	CTO
ACC	NELLIS AFB	RKMF220089	CONSTRUCT BEDDOWN SITE 800 RHG (RH)	Base		Construction	CTO
ACC	NELLIS AFB	RKMF240002	CONSTRUCT RAPID AIRFIELD DAMAGE RECOVERY TRAINING RUNWAY	823 RHS	DB	Construction	CTO
ACC	NELLIS AFB	RKMF240006	CONSTRUCT VEHICLE STORAGE & MAINTENANCE FACILITY PEB (RH)	Base		Construction	CTO
ACC	NELLIS AFB	RKMF210085	RENOVATE 99 CES DORM 794	USACE	DB	Construction	CTO
ACC	SEYMOUR JOHNSON AFB	VKAG171083	CONSTRUCT ADDITION/REPAIR CDC, BLDG 3710	USACE	DB	Construction	CTO
ACC	SEYMOUR JOHNSON AFB	VKAG131046	REPAIR FIRE ALARM CONTROL PANELS FOR MULTIPLE DORMS	Base	DB	Construction	CTO
ACC	SHAW AFB	VLSB160007	DSN-REPAIR ROOF B1200	TBD		Design	CTO
AETC	COLUMBUS AFB	EEPZ121003	REPAIR PILOT TRAINING DORM HVAC/PLUMBING/INTERIOR FINISHES,	Base	DB	Construction	CTO
AETC	GOODFELLOW AFB	JCGU214002	CNSLD/DEMO CONVERT FACILITY FOR LRS, B340	Base		Construction	CTO
AETC	GOODFELLOW AFB	JCGU144001	REPAIR CYBER NETWORK PROCESSING CENTER, B401	Base	DBB	Construction	CTO
AETC	GOODFELLOW AFB	JCGU204006	REPAIR PIPELINE STUDENT DORM, B3210	Base	DBB	Construction	CTO
AETC	HOLLOMAN AFB	KWRD180123	CONSTRUCT MARSHALLING AREA, EOR D	823 RHS	DB	Construction	CTO
AETC	JB SAN ANTONIO	TYMX206613	DSN-Repair Randolph West Runway Drainage, B11106	Base	DBB	Design	CTO
AETC	JB SAN ANTONIO	TYMX121009	Repair 12 FTW Dorm B861	Base	DBB	Construction	CTO
AETC	JB SAN ANTONIO	JBSF180155	Repair Base Defense Operations Center - BDOC, 2244	Base	DBB	Construction	CTO
AETC	KEESLER AFB	MAHG181097	CNSLD/DEMO Locker House, B3101	Base	DBB	Construction	CTO
AETC	KEESLER AFB	MAHG151053	REPAIR STUDENT DORM DAVIS MANOR B6955	Base	DBB	Construction	CTO
AETC	KEESLER AFB	MAHG161017	REPAIR STUDENT DORM SMITH MANOR B7315	Base	DBB	Construction	CTO

FY23 USAF & USSF CONSTRUCTION TASKING ORDER							
MAJCOM	Installation	Project Number	Project Title	Execution Agent	Execution Method	Remarks	CTO/UPL
AETC	LAUGHLIN AFB	MXDP141022	REPAIR/REPLACE LINER, WASTE WATER LAGOON 1	Base	DB	Construction	CTO
AETC	LUKE AFB	NUEX091506	DSN-REPLACE WATER MAINS, VALVES, HYDRANTS 1-5-6-9-1000 AREAS	Base		Design	CTO
AETC	LUKE AFB	HXCZ192200	REPAIR AIRFIELD LIGHTING SYSTEM, GILA BEND AFAP	Base		Construction	CTO
AETC	MAXWELL AFB	PNQS181499	REPR SHOWERS, OTS CADET DORM BLDGS 1486, 1488, 1489, 1491	Base		Construction	CTO
AETC	VANCE AFB	XTLF191014	Renovate Officer Unaccompanied Housing - F643	Base	DBB	Construction	CTO
AETC	VANCE AFB	XTLF191015	Renovate Officer Unaccompanied Housing - F644	Base	DBB	Construction	CTO
AFGSC	BARKSDALE AFB	AWUB210008	Renovate CDC East, B3725	Base	DBB	Construction	CTO
AFGSC	BARKSDALE AFB	AWUB210009	Renovate Dorm 4341 Deficiencies	Base	DB	Construction	CTO
AFGSC	DYESS AFB	FNWZ210068	CNSLD/DEMO 77 WPS/377 TES 7233	Base	DB	Construction	CTO
AFGSC	ELLSWORTH AFB	FXBM244353	DSN-Repair Critical Runway Infrastructure and Utility Systems	USACE		Design	CTO
AFGSC	ELLSWORTH AFB	FXBM151079-1	Primary Surface Bash Hazard	Base		Construction	CTO
AFGSC	ELLSWORTH AFB	FXBM218323	Repair Secure Space BW/HQ B7925	Base		Construction	CTO
AFGSC	FRANCIS E. WARREN AFB	GHLN234885	CNSLD/DEMO B233 To B288	Base	DBB	Construction	CTO
AFGSC	FRANCIS E. WARREN AFB	GHLN222646	Repair Structural Integrity NCO Dorm Bldgs. 222, 223, 224 & 226	Base	DBB	Construction	CTO
AFGSC	FRANCIS E. WARREN AFB	GHLN220840	TTP - Repair/Replace Water Wells at J-01 and K-01 (FAC 118)	823 RHS	DBB	Troop Training	CTO
AFGSC	MALMSTROM AFB	NZAS200017	Reconfigure & Repair Airfield for MH-139 Beddown	Base	DBB	Construction	CTO
AFGSC	VANDENBERG AFB	XUMU171116B	Repair HVAC System, B1546	Base	DB	Construction	CTO
AFGSC	WHITEMAN AFB	YWHG120103	Replace Degraded Process Equipment at WWTP	USACE	DBB	Construction	CTO
AFMC	EDWARDS AFB	FSPM19P5037	MC CONSTRUCT INERT MUNITIONS STORAGE, B637	Base		Construction	CTO
AFMC	EDWARDS AFB	FSPM181431	RPR ELECTRICAL SUBSTATION 14 B8793	TBD		Construction	CTO
AFMC	EDWARDS AFB	FSPM19P5072	RPR MAIN HANGAR ROOF B1600	Base		Construction	CTO
AFMC	EDWARDS AFB	FSPM181420	RPR PLUMBING SYSTEMS HANGAR B1600	Base		Construction	CTO
AFMC	EDWARDS AFB	FSPM19P5055	RPR RAMP 2 PAVEMENT	Base		Construction	CTO
AFMC	ROBINS AFB	UHHZ990029	DSN-RPR/RPL HVAC SYSTEM, BAY A & HEADHOUSE/ROOF (HEADHOU	Base	DBB	Design	CTO
AFMC	ROBINS AFB	UHHZ180028	REMOVE/REPLACE CONCRETE ON TRANSIENT APRON B3955 ADJACEN	Base	DB	Construction	CTO
AFMC	SI HANSCOM	MXRD190075	Repair (Install) Base-wide Radio Fire Alarm System,B1721	Base	DB	Construction	CTO
AFMC	TINKER AFB	WWWYK170096	DSN-CONVERT AREA FOR COMM SQ CONSOL, B3001G	Base	DBB	Design	CTO
AFMC	WRIGHT PATTERSON AFB	ZHTV160020	REPAIR HVAC AHU'S 1, 2, & 4 AND CHILLERS 88CG F/10271	USACE	DBB	Construction	CTO
AFMC	WRIGHT PATTERSON AFB	ZHTV081961	REPAIR ROAD RETAINING WALL / COOLING TOWER FOUNDATION F/21	Base	DBB	Construction	CTO
AFSOC	EGLIN AFB	FTFA20CB28	TTP-CONSTRUCT NEW SMALL ARMS RANGE - 24 SOW	820 RHS	DB	Troop Training	CTO
AFSOC	HURLBURT FIELD	FTEV121164	Add/Alter CDC Main, Bldg 90353, 1 SOFSS	Base	DBB	Construction	CTO
AFSOC	KIRTLAND AFB	MHMV210019	Construct Hayman Structure, Munitions Area	TBD	DB	Construction	CTO
AFSOC	KIRTLAND AFB	MHMV220011	Site Prep for Fabric Sim Structure, ACT, and GTR, B949	TBD	DB	Construction	CTO
AMC	DOVER AFB	FJXT071024P6	Bury Overhead Primary Electric Lines 6 of 6 Phases	Base	DB	Construction	CTO
AMC	JB MCGUIRE DIX LAKEHURST	PTFL181201	REPAIR AIRFIELD ASPHALT MCGUIRE RUNWAY 06/24 KEEL	Base	DBB	Construction	CTO
AMC	JB MCGUIRE DIX LAKEHURST	PTFL111018	REPAIR DORMITORY, B2620	Base	DB	Construction	CTO
AMC	JB MCGUIRE DIX LAKEHURST	PTFL101009	REPAIR ENCLOSURE DORM EXIT STAIR TOWERS, B2622	Base	DBB	Construction	CTO
AMC	JB MCGUIRE DIX LAKEHURST	PTFL211021	REPAIR STORM DRAIN SYSTEM UNDER AIRFIELD MAIN RAMP	Base	DBB	Construction	CTO
AMC	SCOTT AFB	VDYD210067	REPAIR, FSDs & New Sensor Array System, 375 OSS; B433	TBD		Construction	CTO
AMC	SCOTT AFB	VDYD210068	REPAIR, FSDs & New Sensor Array System, 375 OSS; B506	TBD		Construction	CTO
PACAF	EIELSON AFB	FTQW222601	Dorm Roof Repair (MULTI)	TBD		Construction	CTO
PACAF	EIELSON AFB	FTQW042440	DSN-Repair Fire Suppression System (B3425)	TBD		Design	CTO
PACAF	JB ELMENDORF RICHARDSON	FXSB111052	CNSLD/DEMO RECEIVER SITE BUILDING	Base		Construction	CTO
PACAF	JB ELMENDORF RICHARDSON	FXSB221002	Construct K-Span Heavy equipment storage, Camp Mad Bull	RHS		Construction	CTO
PACAF	JB ELMENDORF RICHARDSON	HJZH211099	DEMOLISH UNACCOMPANIED HOUSING MULTI FAC	Base		Demolition	CTO
PACAF	JB ELMENDORF RICHARDSON	FXSB211082	REPAIR COMMUNICATIONS FAC B10488	Base		Construction	CTO
PACAF	KADENA AB	LXEZ201081	REPAIR ROOFS, MULTI	TBD	DBB	Construction	CTO
PACAF	KUNSAN AB	MLWR231010	Repair Pavement at Runway & Overrun	TBD		Construction	CTO
PACAF	MISAWA AB	QKKA171042	DSN-REPAIR DORM, B542	Base		Design	CTO
PACAF	MISAWA AB	QKKA211045	REPAIR COMMAND POST, B928	Base		Construction	CTO
PACAF	SI OSAN	SMYU211104	DEMO ABANDONED B729, 731, 732, & 734	Base		Demolition	CTO
PACAF	SI OSAN	SMYU211113	DEMO ABANDONED B918, 930 & 1012	Base		Demolition	CTO
PACAF	SI OSAN	SMYU201071	DEMO VACANT B178, 311, 411, 421, 506, 840, 929, 1335, 1765 & 1822	Base		Demolition	CTO
PACAF	SI OSAN	SMYU231012	DSN-REPAIR AIRMAN DORMITORY, B1458	USACE		Design	CTO
PACAF	SI OSAN	SMYU221003	REPAIR AIRFIELD PAVEMENTS, FY23	USACE		Construction	CTO
PACAF	SI OSAN	SMYU211012	REPAIR COLLECTIVE PROTECTION SYSTEM FOR HTACC, B935	USACE		Construction	CTO
PACAF	SI TAEGU	WNHQ211101	CONSTRUCT PARKING APRON FOR LAMS, PHASE2, SUWON	USACE		Construction	CTO
PACAF	SI TAEGU	MEPZ211403	CONSTRUCT SEWER SYSTEM AT MAINTENANCE AREA	USACE		Construction	CTO
PACAF	SI TAEGU	WPZQ181203	REPAIR TRANSIENT TRAINING ENLISTED BARRACKS, B-502	USACE		Construction	CTO
PACAF	SI TAEGU	WPZQ181204	REPAIR TRANSIENT TRAINING ENLISTED BARRACKS, B-503	USACE		Construction	CTO
PACAF	SI TAEGU	MMFZ208302	REPLACE ABOVE GROUND FUEL STORAGE TANKS, KWANGJU AB	USACE		Construction	CTO
PACAF	SI TAEGU	MEPZ201202	UPGRADE D-21 FIRE ALARM SYSTEM, COBs	USACE		Construction	CTO
PACAF	YOKOTA AB	ZNRE054320	DSN-Renovate DORM B118	Base		Design	CTO
PACAF	YOKOTA AB	ZNRE172528	Renovate Kitchen, Multi-Dorms	Base		Construction	CTO
PACAF	YOKOTA AB	ZNRE201095	Repair HVAC System, Multi-Dorms	Base		Construction	CTO
PACAF	YOKOTA AB	ZNRE221017	Replace Constant Current Regulators, B1370	Base		Construction	CTO
PACAF	YOKOTA AB	ZNRE221016	Replace Slabs, Taxiway A North	Base		Construction	CTO
PACAF	YOKOTA AB	ZNRE201118	TTP - F8 Airfield Keyhole Expansion	Base		Troop Training	CTO
USAFE	USAF ACADEMY	XQPZ190215	Rpr EMCS Network to VLAN	Base	DBB	Construction	CTO
USAFE	AVIANO AB	ASHE121039	CNSLD/DEMO COMMUNITY CENTER BLDG 1469	Base	DBB	Construction	CTO
USAFE	INCIRLIK AB ADANA	LJYC111002	RPR DORM 882 (Bridge Plan)	Base	DB	Construction	CTO
USAFE	INCIRLIK AB ADANA	LJYC231086	RPR DORM 894	Base	DB	Construction	CTO
USAFE	INCIRLIK AB ADANA	LJYC231097	RPR DORM 896	Base	DB	Construction	CTO
USAFE	INCIRLIK AB ADANA	LJYC231088	RPR HERKY UH, BLDGS 2745-2754	Base	DB	Construction	CTO
USAFE	LAJES FIELD	MQNA221000	CNSLD/DEMO Security Forces Operations into T-810	Base	DB	Construction	CTO
USAFE	LAJES FIELD	MQNA051035A	Repair ATC Tower/Pumphouse Fire Suppression	Base	DB	Construction	CTO
USAFE	LAJES FIELD	MQNA211502	Repair Pavement on Taxiway Juliet	Base	DB	Construction	CTO
USAFE	MORON AB	QUUG141003	CNS POTABLE WATER TREATMENT FACILITY	Base	DBB	Construction	CTO
USAFE	MORON AB	QUUG161018	RPR 1ST STREET	CTS	DB	Construction	CTO

FY23 USAF & USSF CONSTRUCTION TASKING ORDER							
MAJCOM	Installation	Project Number	Project Title	Execution Agent	Execution Method	Remarks	CTO/UPL
USAFE	MORON AB	QUUG161007	RPR 'C' AVENUE, F2006	CTS	DB	Construction	CTO
USAFE	RAF ALCONBURY	AEDY204001	Repair, Bathrooms - Enlisted Dormitory, B652	DIO	DB	Construction	CTO
USAFE	RAF ALCONBURY	AEDY214006	Repair, Enlisted Dormitory, B652	DIO	DB	Construction	CTO
USAFE	RAF LAKENHEATH	GPLS220003	CNSLD/DEMO SECURITY FORCES, TO B38 FROM B49	DIO	DB	Construction	CTO
USAFE	RAF LAKENHEATH	MSET192020PA	DSN-REPAIR 917 DORMITORY PHASE 1	DIO		Design	CTO
USAFE	RAF LAKENHEATH	MSET162058	REPLACE UST'S WITH AST'S, BLDG 946 DORMITORY	DIO	DBB	Construction	CTO
USAFE	RAMSTEIN AB	YANB211566	ADD/ALTER/CONVERT B#1058 FOR SATELLITE FIRE STATION	CTS	DB	Construction	CTO
USAFE	RAMSTEIN AB	TYFR091216	RENOVATE/MOLD REMEDIATION DORMITORY, B#2418	LBB	DBB	Construction	CTO
USAFE	RAMSTEIN AB	TYFR211062	SUS/REPAIR APPROACH LIGHTING AND FLASHING LIGHTS RUNWAY SC	Base	DB	Construction	CTO
USAFE	RAMSTEIN AB	TYFR211070	SUS/REPAIR WATER LINES LAWN/HARMON/MADISON AVE, B#5820	Base		Construction	CTO
USAFE	SPANGDAHLEM AB	VYHK211001	REPAIR BACKFLOW PREVENTION DEFICIENCIES AT MULTI FACILITIES, B	Base		Construction	CTO
USAFE	SPANGDAHLEM AB	VYHK201645	REPAIR OIL WATER SEPARATOR DEFICIENCIES BASEWIDE	Base		Construction	CTO
USSF	CAVALIER AIR STATION	EGYN161004	RPR & RELINE MISSION CRITICAL COOLING WATER PIPING B820-830	TBD		Construction	CTO
USSF	CHEYENNE MOUNTAIN SFS	SAXC211008	Repair Blast Valve Control System - CMC	Base	DB	Construction	CTO
USSF	EGLIN AFB	FTFA101100	DSN-RENOVATE 4TH FLOOR INTEGRATION OPERATIONS CENTER, BLDG	Base	DBB	Design	CTO
USSF	FORT MACARTHUR FAMILY HOU	HHEK151025	REPAIR B33 DORM, BUILDING SYSTEMS, FT. MAC.	Base	DB	Construction	CTO
USSF	JONATHAN DICKINSON MISSILE	JJAE181504	Repair Missile Guidance Station, B28001	Base	DBB	Construction	CTO
USSF	LOS ANGELES SFB	ACJP141016	REPAIR HVAC SYSTEM, B272 SPACE SYSTEMS COMMAND	Base		Construction	CTO
USSF	PATRICK SFB	SXHT121042	CNSLD/DEMO for Courtroom, B402	Base	DBB	Construction	CTO
USSF	PATRICK SFB	SXHT921065	Repair/Upgrade Engineering, B534	Base	DBB	Construction	CTO
USSF	PETERSON SFB	TDKA151029	DEMO DORMS 1102, 1154, 1156	Base	DB	Demolition	CTO
USSF	RAMSTEIN AB	TYFU211501	UPGRADE ELECTRICAL POWER GRID	Base	DBB	Construction	CTO
USSF	SCHRIEVER SFB	GLEN131036	Repair Replace RA Perimeter Lighting	Base	DBB	Construction	CTO
USSF	SCHRIEVER SFB	GLEN201009	Repair Roof Bldg 700	USACE	DBB	Construction	CTO
USSF	THULE AB	WWCX181001	Repair Roof, B4002	USACE	DBB	Construction	CTO
USSF	VANDENBERG SFB	XUMU201060B	ROTF Repair HVAC and Build Wall at B15501	Base	DB	Construction	CTO
USSF	VANDENBERG SFB	XUMU091708B	ROTF Replace Transformer A1	Base	DB	Construction	CTO
USSF	VANDENBERG SFB	XUMU121223B	Upgrade Fire Suppression System B10577	Base	DB	Construction	CTO
ACC	DAVIS MONTHAN AFB	FBNV120023	Demo Facility 3501	TBD		Demolition	UPL
ACC	DAVIS MONTHAN AFB	FBNV190002	EA - Repair/Construct Primary Electric Distribution for Energy Resilienc	TBD		Design	UPL
ACC	SHAW AFB	VLSB230002	REPAIR ROOFS MULTI FIRE STATION AND SHOPS	TBD		Construction	UPL
ACC	SI OSAN	SMYU161074	REPAIR CONTROLLED RM K213 in KCOIC, B940	USACE	DBB	Construction	UPL
AETC	ALTUS AFB	AGGN231001	Repair Child Development Center B53	Base		Construction	UPL
AFDW	JB ANDREWS	AJXF181532	REPAIR BUILDINGS 1220 & 1245	TBD		Construction	UPL
AFGSC	DYESS AFB	FNWZ160046	Construct/Repair Changing Room, 5112 Paint Hangar	Base		Construction	UPL
AFGSC	ELLSWORTH AFB	FXBM224594	Repair Distribution Transformers	Base		Construction	UPL
AFGSC	ELLSWORTH AFB	FXMB229366	REPAIR OPERATIONAL APRON ASPHALT PAVEMENT	Base		Construction	UPL
AFGSC	MINOT AFB	QJVF193368	Repair MAF Actuated Gates, Multi (Umbrella)	TBD		Construction	UPL
AFMC	EDWARDS AFB	FSPM162541	MC VEHICLE SEARCH AREA AFRL GATE ECP	TBD		Construction	UPL
AFMC	EDWARDS AFB	FSPM22P5003	RPR EXTERIOR ENCLOSURE TW HQ B2750	TBD		Construction	UPL
AFMC	EDWARDS AFB	FSPM031448	RPR FIRE SUPPRESSION SYSTEM FUEL CELL MAINT B1622	TBD		Construction	UPL
AFMC	EDWARDS AFB	FSPM125608	RPR PCC PAVEMENT A38B PAD 5	Base		Construction	UPL
AFMC	ROBINS AFB	UHHZ210473	REMOVE/REPLACE SLABS AND MTN/PAINT RUNWAY, RUNWAY, 3901	TBD		Construction	UPL
AFMC	TINKER AFB	WWWK040332	DEMO B477, OLD COMMISSARY (CLEAR ZONE)	TBD		Demolition	UPL
AMC	JB CHARLESTON	DKGV223225	REPAIR (SUS) CONSOLIDATED BRIG HVAC, B.3107	TBD		Construction	UPL
AMC	JB MCGUIRE DIX LAKEHURST	PTFL172007	REPAIR FIRE SUPPRESSION SYSTEM, HANGAR 3209	Base		Construction	UPL
AMC	MCCONNELL AFB	PRQE170131	REPAIR AIR HANDLING UNITS DOLE COMMUNITY CENTER BLDG 412	TBD		Construction	UPL
AMC	SCOTT AFB	VDYD191122	REPAIR, Roof, Exterior Walls & HVAC Renovations, USTC; B1900	Base		Construction	UPL
PACAF	EARECKSON AS	YGFZ190010	Demolish Vehicle Ops Parking Shed (B1407)	USACE		Demolition	UPL
PACAF	EIELSON AFB	FTQW171015	Renovate CAC (B1300)	TBD		Construction	UPL
PACAF	EIELSON AFB	FTQW191013	Repair Fire Suppression System in CHPP (B6203)	TBD		Construction	UPL
PACAF	JB ELMENDORF RICHARDSON	FXSB211083	RENOVATE SATCOM FACILITY B5385	Base		Construction	UPL
PACAF	JB ELMENDORF RICHARDSON	FXSB171504	REPAIR FIRE SUPPRESSION & HVAC B9480	Base		Construction	UPL
PACAF	JB ELMENDORF RICHARDSON	FXSB181265	REPAIR STORMWATER PIPE CRAW TO ARNOLD	Base		Construction	UPL
PACAF	KADENA AB	LXEZ181441	REPAIR AIRCRAFT MAINTENANCE HANGAR, B780	Base		Construction	UPL
PACAF	SI OSAN	SMYU211020	REPAIR 18 INTEL SQUADRON OPERATIONS, B322	USACE		Construction	UPL
PACAF	SI TAEGU	MMFZ191305	INSTALL FIRE SUPPRESSION SYSTEM, MULTI AT KIMHAE & KWANGJU	USACE		Construction	UPL
PACAF	SI TAEGU	WNHQ171115	REPAIR TELECOMMUNICATIONS FACILITY, B-2005	USACE		Construction	UPL
PACAF	SI TAEGU	MMFZ181307	REPAIR UNACCOMPANIED PERSONNEL QUARTERS, B-243	USACE		Construction	UPL
PACAF	YOKOTA AB	ZNRE201093	Replace Sequenced Flashing Lights, North	Base		Construction	UPL
USAFE	AVIANO AB	ASHE211011	INSTALL BASE PERIMETER CAMERAS	Base		Construction	UPL
USAFE	RAF CROUGHTON	EXSW161018	INSTALL SPRINKLER SYSTEM AND INTERNAL MODIFICATIONS	DIO		Construction	UPL
USAFE	RAF MILDENHALL	QFOE222003	REPAIR AIRCRAFT CORROSION CONTROL FACILITY, B711	DIO		Construction	UPL
USSF	BUCKLEY SFB	CRWU201027	Repair by Replace Roofs Multi	TBD		Construction	UPL
USSF	CAPE CANAVERAL SFS	DBEH021675	(ROTF) Repair Primary Distribution "B" Line Overhead B21903	TBD		Construction	UPL
USSF	CLEAR SFS	DXEB021009	REPAIR MOTOR POOL VENT/EXHAUST SYSTEM	USACE		Construction	UPL
USSF	KAENA POINT	LXHY202001	Replace, Fire Protection Waterline Pressure Regulating Valve System a	USACE		Construction	UPL
USSF	LOS ANGELES AFB	HHEK171179	REPAIR HVAC SYSTEM ALT.COMMAND POST, B410, FT. MAC.	TBD		Construction	UPL
USSF	RAMSTEIN AB	TYFU201574	CONSTRUCT ANTENNA FOUNDATION AND GENERATOR FACILITY KAPA	Base		Construction	UPL
Estimated Project Value \$5M - \$10M							
ACC	BEALE AFB	BAEY203001	Repair Jr. Enlisted Airmen Dormitory, B24110	Base	DB	Construction	CTO
ACC	BEALE AFB	BAEY203002	Repair Jr. Enlisted Airmen Dormitory, B24114	Base	DB	Construction	CTO
ACC	MOUNTAIN HOME AFB	QYZH200001	ADD/ALT Dorm B2425	Base	DBB	Construction	CTO
ACC	SEYMOUR JOHNSON AFB	VKAG091012	REPAIR PERMANENT PARTY ENLISTED DORMITORY,B3607	Base	DBB	Construction	CTO
AETC	COLUMBUS AFB	EEPZ133000	CNSLD/DEMO AIRCRAFT MX ADMIN/OPERATIONS FACILITY, B634/640	USACE	DBB	Construction	CTO
AETC	GOODFELLOW AFB	JCGU154001	REPAIR PIPELINE STUDENT DORM, B3206	Base	DBB	Construction	CTO
AFDW	JB ANDREWS	AJXF201500	REPAIR DORMITORY, BUILDING 1690	Base	DBB	Construction	CTO
AFGSC	MINOT AFB	QJVF120044	Renovate Dorm 131	USACE	DB	Construction	CTO
AFMC	TINKER AFB	WWWK190219	REPAIR DORMITORY, B5913	Base		Construction	CTO

FY23 USAF & USSF CONSTRUCTION TASKING ORDER

MAJCOM	Installation	Project Number	Project Title	Execution Agent	Execution Method	Remarks	CTO/UPL
AFMC	WRIGHT PATTERSON AFB	ZHTV160060	REPAIR AHU-5 NASIC F/10856	USACE	DBB	Construction	CTO
AFSOC	KIRTLAND AFB	MHMV180079	Renovate Island B, H1002, 58 SOW	TBD	DB	Construction	CTO
AMC	DOVER AFB	FJXT121092	Repair Dorm 430	Base	DB	Construction	CTO
AMC	JB CHARLESTON	DKFX151048	RPR (SUS) FLIGHT SIMULATOR FACILITY - B.108	TBD		Construction	CTO
AMC	LITTLE ROCK AFB	NKAK203000	Convert Mission Planning Cell B380	TBD		Construction	CTO
HAF	TYNDALL AFB	AFCE2300P8	Deploy AMRS at Various Bases - FY23	TBD		Construction	CTO
PACAF	EIELSON AFB	FTQW071096	Repair Taxiway Alpha & Foxtrot North	TBD		Construction	CTO
USSF	ASCENSION AUXILIARY AIRFIELD	YXTK181805	Repair/Cvrt 15kV Switchgear and Controls, B21905	TBD		Construction	CTO
USSF	BUCKLEY SFB	CRWU171040	Repair by Replace HVAC Space Operations Facility B430	Base	DBB	Construction	CTO
USSF	VANDENBERG WATER SUPPLY A	XUYF161091B	ROTF Repair Overhead Distribution Line, Oak Mountain Feeder	Base	DB	Construction	CTO
ACC	BEALE AFB	BAEY211006	Repair Watermain, 18-inch Return Line; 3 MG Tank to Flightline	Base		Construction	UPL
ACC	GRAND FORKS AFB	JFSD201808	ADD/RPR CDC FOR COMPLIANCE & RECAPITALIZATION B168	Base		Construction	UPL
AETC	ALTUS AFB	AGGN200002	Repair Maintenance Dock Hangar B285	Base		Construction	UPL
AFMC	HILL AFB	KRSM100042PE	REPAIR AIR FREIGHT APRON B5000 Phase E	TBD		Construction	UPL
AFMC	WRIGHT PATTERSON AFB	ZHTV130006PA	DSN-RENOVATE AFLCMC ADMIN FACILITY, PHASE 1, F/20016	Base		Design	UPL
USSF	ASCENSION SFS	YXTK121809	Repair Dormitory 14	TBD		Construction	UPL
Estimated Project Value \$10M - \$25M							
AETC	HOLLOMAN AFB	KWRD190010	ADD/ALTER BLOCK 42 F-16 FTU OPS FACILITY, B105	USACE	DBB	Construction	CTO
AETC	HOLLOMAN AFB	KWRD180139	REPAIR DORM, B334	Base	DB	Construction	CTO
AETC	JB SAN ANTONIO	MPLS170261	Repair Mesquite Dining Facility, B10175	Base	DBB	Construction	CTO
AETC	JB SAN ANTONIO	JBSF180119	Repair Plumbing Infrastructure, B1350	Base	DBB	Construction	CTO
AETC	KEESLER AFB	MAHG111042	Repair Bryan Hall Cyber Training B6901	Base	DBB	Construction	CTO
AFDW	JB ANDREWS	AJXF181523	REPAIR EX WALLS, WINDOWS, EX DOORS, ROOF, IN WALLS, IN DOORS	Base	DBB	Construction	CTO
AFDW	JB ANDREWS	AJXF191590	REPAIR HANGAR 4, BUILDING 1734	Base	DBB	Construction	CTO
AFGSC	DYESS AFB	FNWZ210047PA	Repair Main Parking Ramp 505 PA	Base	DB	Construction	CTO
AFMC	ARNOLD AFB	ANZY139051	RENOVATE ETF OFFICE SPACES, B877	Base		Construction	CTO
AFMC	HILL AFB	KRSM100042PC	REPAIR EAST 388TH/419TH FW F-35 APRON B5000 Phase C	USACE	DB	Construction	CTO
AFMC	TINKER AFB	WWYK180046	REPAIR INDUSTRIAL WASTE SYSTEM, TAC COMPLEX	USACE	DBB	Construction	CTO
AFMC	TINKER AFB	WWYK190218	REPAIR MIDKIFF HALL, DORMITORY, B5903	Base	DB	Construction	CTO
AMC	LITTLE ROCK AFB	NKAK211034	Repair (SUS) Airmen Dormitory B854	Base	DB	Construction	CTO
AMC	TRAVIS AFB	XDAT181080	Repair Enlisted Dorm 1331	NAVFAC	DB	Construction	CTO
AMC	TRAVIS AFB	XDAT181081	Repair Enlisted Dorm, B1332	USACE	DB	Construction	CTO
PACAF	EARECKSON AS	VNMH140006	Repair Site Fire Alarm System	USACE		Construction	CTO
PACAF	KADENA AB	LXEZ101310	REPAIR ENLISTED DORM, B141	TBD	DB	Construction	CTO
PACAF	YOKOTA AB	ZNRE181048	Renovate Dorm Tower 2091	Base		Construction	CTO
USSF	CHEYENNE MOUNTAIN SFS	SAXC211013P3	Refurbish Diesel Generators - CMC Phase 3	Base	DB	Construction	CTO
AFDW	JB ANDREWS	AJXF151700	REPAIR STORMWATER FOR 7 OUTFALLS & SECURITY FENCE	TBD		Construction	UPL
AFMC	SI HANSCOM	MXRD170051	Repair Child Development Center, B1994	TBD		Construction	UPL
PACAF	YOKOTA AB	ZNRE141067	Renovate Tower 2085	TBD		Construction	UPL
USSF	CHEYENNE MTN SFS	SAXC211013P4	Refurbish Diesel Generators - CMC Phase 4	Base		Construction	UPL
USSF	CHEYENNE MTN SFS	SAXC211013P5	Refurbish Diesel Generators - CMC Phase 5	Base		Construction	UPL
USSF	THULE AB	WWCX103007	REPAIR HIGH RISE DORMITORY, BLDG 99	USACE		Construction	UPL
Estimated Project Value > \$25M							
ACC	BEALE AFB	BAEY211000	Repair/Construct Intelligence Surveillance Reconnaissance (ISR) Facility	AFCEC	DBB	Construction	CTO
AETC	JB SAN ANTONIO	MPLS203959	Repair/Renovate Recruit Housing & Training Dorm, B10416	AFCEC	DBB	Construction	CTO
PACAF	JB ELMENDORF RICHARDSON	FXSB181003	REPAIR TURNAGAIN DORM B8113	USACE		Construction	CTO
USAF	USAF ACADEMY	XQPZ200015	Rpr Cadet Field House, Ph 3	USACE	DBB	Construction	CTO
USSF	LOS ANGELES SFB	ACJP192031B	SPACE ACQUISITION MISSION B271 3RD FLOOR, LAAFB	AFCEC	DB	Construction	CTO
PACAF	JB ELMENDORF RICHARDSON	HJZH111031	RENOVATE ATTU HALL B977	USACE		Construction	UPL
PACAF	JB ELMENDORF RICHARDSON	FXSB211062	RENOVATE HANGAR 2 B11525	USACE		Construction	UPL
USSF	CAPE CANAVERAL SFS	DBEH171568	(ROTF) Repair Cape Canaveral SFS Runway, B50305	TBD		Construction	UPL
USSF	THULE AB	WWCX172002	Repair BMEWS Power, Building 4016	USACE		Construction	UPL